



zgx





⚠ WARNING

WARNING! Stored Energy Hazard:
 The arm mechanism is under tension and will move up rapidly, on its own, as soon as attached equipment is removed. For this reason, **DO NOT** remove equipment unless the arm has been moved to the highest position! Failure to follow this instruction may result in serious personal injury and/or equipment damage!

zgo | technologies **BACHMANN**
Optimal Performance. Infinite Design. www.bachmann.com

